

JOYCE/DAYTON CORP. Job Description

Position Title: General Machinist - CNC Operator - Mill & Lathe

Reports To: Manufacturing Manager

Qualifications:

Basic programming knowledge and or experience.

- Sound mechanical aptitude with hands on skills.
- Minimum of a high school degree and or related experience commensurate with position responsibilities.
- Strong written and verbal communication skills.
- Basic understanding of equipment and processes in area of responsibility.
- Effective people skills.
- Minimum Requirements:
 - Ability to read precision measuring equipment.
 - Own basic tools.
 - Basic blue print reading skills.
 - Basic product knowledge.
 - o Capable of understanding and following routing information.
 - Basic set-up capabilities.
 - Basic tooling knowledge.
 - Basic understanding of feeds and speeds.
 - Minimum of 2 years proven experience.
 - Minimal layout capabilities.
 - o Some fixturing knowledge.
 - Very minimal direction required.
 - o Technical training as required.

General Responsibilities:

- 3-5 years of related CNC operating and setup experience preferred.
- Coordinate efforts to safely and efficiently produce product that meets all quality parameters.
- Maintain and set-up various jobs on CNC Mills/Lathes.

Specific Responsibilities:

- Demonstrate a thorough understanding of tooling and fixtures for a large variety of work arrangements.
- Capable of identifying and communicating recommendations for product and productivity enhancements (lean initiatives).
- Work in team environment with material schedulers to support customer needs.
- Demonstrate a sound level of programming knowledge.
- Demonstrate the ability to modify programs to support changes in materials and or scheduling revisions.
- Demonstrate effective blue print reading skills.
- Possess effective measuring equipment utilization skills.
- Maintain compliance with company policy, safety and good housekeeping practices.
- Able to work closely in a teamwork environment.
- Able to prioritize work in an efficient and productive manner.
- Responsible for basic up keep and cleanliness of machines and area.
- Ability to trouble shoot machines as needed.
- Demonstrated willingness and ability associated with being a self-starter.
- Ability to motivate co-workers for continuous quality improvement.
- Ability to keep scrap and rework at minimal levels as defined.
- Overhead crane experience.
- Fork truck experience.
- Meet physical requirements.
- Additional duties as assigned.